

TYPE OF EXHIBIT: Part 15 Label

FCC PART: 15.19(a)(3)

MANUFACTURER: RITRON, INC.
505 West Carmel Drive
Carmel, IN 46032

MODELS: RQT-433-RCVR

TYPE OF UNIT: 433.92 MHz Keyfob Receiver

FCC ID: AIERIT32-433-RCVR

DATE: January 30, 2012

Pursuant to CFR 47 Part 15.19(a)(3) a label with the following Part 15 warning statement will be placed on the RQT model enclosure in which the Part 15B receiver is installed. This statement will also be included in the product instruction manual.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Signed: Michael A. Pickard
Michael A. Pickard - Project Engineer

Location of Part 15
Warning Label

