RUBICOM SYSTEMS, INC.

FCC TEST REPORT

(INTENTIONAL RADIATOR)

FOR THE

ROCKWELL COLLINS, INC.

VHF-4000 COMMUNICATIONS TRANSCEIVER

(118-137MHz)



Rubicom Systems, Inc. 284 West Drive, Suite B Melbourne, FL 32904 THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE WRITTEN APPROVAL OF THE TESTING LABORATORY

FCC TEST REPORT

(INTENTIONAL RADIATOR)

FOR THE

ROCKWELL COLLINS, INC.

VHF-4000 COMMUNICATIONS TRANSCEIVER


(118-137MHz)

S/N: FBLF


PART 6

Prepared by:		
	Joseph G. Barbee	
Tested by:	Alex Belardinelli	
Performed by:		Performed for:
RUBICOM SYSTEMS, INC. 284 West Drive, Suite B Melbourne, Florida 32904		ROCKWELL COLLINS, INC. 1100 W. Hibiscus Blvd. Melbourne, Florida 32901
Received:	September 9, 2001	


Completed: September 12, 2001



DATA SHEET 6.1-16



DATA SHEET 6.1-17



DATA SHEET 6.1-18