

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1



Photo 2

Worst Case Position

**Below 1GHz (Horizontal: X-axis/ Vertical: X-axis)
Above 1GHz (Horizontal: X-axis/ Vertical: Y-axis)**

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN
Telephone : +81 596 24 8999
Facsimile : +81 596 24 8124