


8. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP – ABOVE 1 GHz





RADIATED RF MEASUREMENT SETUP – BELOW 1 GHz





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP – without USB Charging Cable





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP – with USB Charging Cable



LINE CONDUCTED BACK PHOTO



END OF REPORT