

dward

To: toriw@mflom.com; SandyV@mflom.com; hoosam@mflom.com; jackie@mflom.com
Cc: customerservice@atcb.com
Subject: www.AmericanTCB.com ATCB006723 | ALH30923120 | | ALH30923120_ATCB006723

Regarding www.AmericanTCB.com application:

ATCB ID: ATCB006723

FCC ID: ALH30923120

IC:

TCF:

Account name: mflom

Please correct the 731 form. The original filing is only for part 22 and 90. You have mistakenly listed part 74 in the 731. Please remove this reference.

You have incorrectly listed head SAR on the website. Please remove this and check Body SAR only.

Please provide a separate cover letter giving more accurate details as to what was changed. For example the external appearance of the device has changed. How? Please provide external photos of the device.

You say that the rf amp has changed components. Please provide the internal photo showing this change.

As with the previous device, this was granted by the FCC prior to the TCB program. I will have to contact them to see if the rf category can be changed.

Thanks