



MFA

M. Flom Associates, Inc. - Global Compliance Center
3356 North San Marcos Place, Suite 107, Chandler, Arizona 85224-1571
www.goodnet.com/~mflom, (602) 926-3100, FAX: 926-3598

TOTAL PAGES:	2
DATE:	January 22nd, 1999
VIA FAX:	1 301 344 2050
TO:	Federal Communications Commission,
ATTENTION:	Frank Coperich, Electronics Engineer
APPLICANT:	KENWOOD COMMUNICATIONS CORPORATION
EQUIPMENT:	FCC ID: ALHTKR-820N-4 Confirm: #EA92154
SUBJECT:	Correspondence Reference #5635

Good morning Frank:

Further to your e-mail of 01/20/99, attached please find copy of Kenwood Service Bulletin which addresses the item in your correspondence.

Trust this now meets the requirements of the Commission and that the Grant will be issued A.S.A.P.

Regards,

MARTHA FLOM, Office Manager

mgf
enc.

KENWOOD

LSB-0219 REV. A

SERVICE BULLETIN

Land Mobile Division

SUBJECT: UHF TRANSCEIVERS CAPABLE OF 406-406.1 MHz TX **DATE:** 09/04/98

The United States Coast Guard and NOAA have reported to the FCC an occurrence of unauthorized transmissions in the 406-406.1 MHz band. This band is reserved for use by distress beacons.

The purpose of this Service Bulletin is to remind all Kenwood Authorized Dealers and Servicers not to program the 406-406.1 MHz frequency range into any Kenwood transceiver capable of transmitting in this frequency range.

NOTE:

This bulletin has been revised to correct the frequency range.

Printed in U.S.A.

Kenwood Service Corporation 2201 E. Dominguez St. Long Beach, Ca. 90810

(310) 761-8275

(310) 761-8290 FAX

(310) 605-5045 BBS

(310) 761-4498 Direct FAX