

Uniden Engineering Services
181 N. Country Club Road
P.O. Box 580
Lake City, SC 29560
Phone (843) 374-3852
Fax (843) 374-8393



January 21, 2005

To: Mr. Andrew Leimer
Federal Communications Commission

Re: FCC ID: AMWUP744R
Applicant: Uniden America Corporation
CRN: 28313

Dear Mr. Leimer:

A typographical error was found in the SAR report. Now both the SAR and EMC reports show the same power. A revised SAR Report is being uploaded along with this cover letter..

The RF Exposure instructions are shown on page 43/53 in the Owner's Manual (Part 2). This is basically the same language that we use for most all of our cordless telephones with similar RF Exposure concerns. A file entitled "RF Exposure information in OM.pdf" is being uploaded for your review.

Concerning item 3 of your email, this was entirely my mistake which I recently uploaded the correct files. Please accept my apologies for this error.

I trust that this information, plus the files being uploaded, provide a satisfactory response to your request as stated in your email of January 12, 2005.

Thank you for your consideration and please contact the undersigned if you have any questions or need any further information.

Regards,

A handwritten signature in black ink that reads "James R. Haynes". The signature is written in a cursive style with a large, stylized initial "J".

James R. Haynes
Vice President, Engineering and Regulatory Affairs

