
Subject: FW: Sharp Corporation , FCC ID: APYDMR0161, Assessment NO.: AN05T4767, Notice#1



05U3347-1 FCC
Repot.pdf

From: Danielle Zhan
Sent: Wednesday, May 04, 2005 12:39 PM
To: Helen Zhao
Subject: RE: Sharp Corporation , FCC ID: APYDMR0161, Assessment NO.:
AN05T4767, Notice#1

Please check the answer from Hitesh below. Thanks!

Regards,

Question #1: Test Report - Section 6.3 RF output power: Please revisit the formula used for calculating the RF output power. The values listed in the table are incorrect. Please recalculate the RF output power.

ANS.- CHANGES MADE

Question #2: Test Report - Section 6.5 Radiated spurious emission limit: the limit is associated with measured RF output power. Since you need to recalculate RF output power (Q2), please recalculate the radiated spurious emission limit and apply the new limit in section 6.5 Radiated emission.

ANS. - CHANGES MADE

Question #3: Test Report - Section 6.5.1 Radiated emission below 1GHz: if there is any offset used during the test, please indicate in the test report.

ANS. - CHANGES MADE

Best Regards,