

Internal Photographs




Figure 1. Cooktop

US Tech Test Report:
Report Number:
Issue Date:
Customer:
FCC ID:
Model:

FCC Part 18 Subpart C Certification
22-0219
August 23, 2022
Sharp Corporation
APYDMR0181
STR3065HS




Figure 2. Side 1

US Tech Test Report:
Report Number:
Issue Date:
Customer:
FCC ID:
Model:

FCC Part 18 Subpart C Certification
22-0219
August 23, 2022
Sharp Corporation
APYDMR0181
STR3065HS




Figure 3. Side 2

US Tech Test Report:
Report Number:
Issue Date:
Customer:
FCC ID:
Model:

FCC Part 18 Subpart C Certification
22-0219
August 23, 2022
Sharp Corporation
APYDMR0181
STR3065HS




Figure 4. Rear

US Tech Test Report:
Report Number:
Issue Date:
Customer:
FCC ID:
Model:

FCC Part 18 Subpart C Certification
22-0219
August 23, 2022
Sharp Corporation
APYDMR0181
STR3065HS




Figure 5. Top of Microwave without Cooktop

US Tech Test Report:
Report Number:
Issue Date:
Customer:
FCC ID:
Model:

FCC Part 18 Subpart C Certification
22-0219
August 23, 2022
Sharp Corporation
APYDMR0181
STR3065HS




Figure 6. Front controls

US Tech Test Report:
Report Number:
Issue Date:
Customer:
FCC ID:
Model:

FCC Part 18 Subpart C Certification
22-0219
August 23, 2022
Sharp Corporation
APYDMR0181
STR3065HS



Figure 7. Wi-Fi Module