



捷聯電子股份有限公司

Top Victory Electronics (Taiwan) Co., Ltd.

18F, No. 738, Chung-Cheng Rd, Chung-Ho, Taipei Hsien, Taiwan
臺北縣中和市中正路738號18樓 TEL: 886-2-82261668 FAX: 866-2-82261666

Letter of Modification

Date: January 16, 2002

Subject : RFI related modifications incorporated into unit with FCC ID. : ARSLM562H

Dear Sir,

This letter serves as our declaration that all modifications listed below are implemented in the sample submitted for pre-grant testing. We further declare that the same modifications will be implemented into all production unit to enhance compliance of the unit to FCC limits.

The modifications include the following :

1. Added 2pcs ferrite cores on the D-Sub signal cable.
@ Refer to Figure 1. (Page 7)
2. Added 2pcs ferrite cores on the DVI signal cable.
@ Refer to Figure 1. (Page 7)
3. Added a ferrite core on the DC power cord of Audio Base.
@ Refer to Figure 8. (Page 10)
4. Added a ferrite core on the cable of OSD control board.
@ Refer to Figure 25. (Page 19)
5. Added a ferrite core on the LVDS cable of LCD Panel.
@ Refer to Figure 27. (Page 20)

If you have any questions or require any other information please do not hesitate to contact our agent.

Sincerely Yours,

George Wang
Manager
Top Victory Electronics (Taiwan) Co., Ltd.