


Internal photographs of MCX-1000A.  
Outside of MCX-1000A with cover in place



Inside layout with top cover removed



ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Honeywell International Inc.  
PN: 42455-1  
Test #: 051212  
Test to: FCC Parts 2, 15 and 87


MODEL: MCX-1000A  
SN: Y1139  
FCC ID#: ASY MCX-1000A

Page 1 of 6


Honeywell MCX1000A Internal Photos 1/9/2006



RT module with cover in place



RT module with cover removed



ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Honeywell International Inc.  
PN: 42455-1  
Test #: 051212  
Test to: FCC Parts 2, 15 and 87


MODEL: MCX-1000A  
SN: Y1139  
FCC ID#: ASY MCX-1000A

Page 2 of 6


Honeywell MCX1000A Internal Photos 1/9/2006



Bottom side of RT module



Buffer




ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Honeywell International Inc.  
PN: 42455-1  
Test #: 051212  
Test to: FCC Parts 2, 15 and 87


MODEL: MCX-1000A  
SN: Y1139  
FCC ID#: ASY MCX-1000A



Transmit board top



Transmit board bottom



ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Honeywell International Inc.  
PN: 42455-1  
Test #: 051212  
Test to: FCC Parts 2, 15 and 87


MODEL: MCX-1000A  
SN: Y1139  
FCC ID#: ASY MCX-1000A

Page 4 of 6


Honeywell MCX1000A Internal Photos 1/9/2006



VCO with cover



VCO with cover removed



ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Honeywell International Inc.  
PN: 42455-1  
Test #: 051212  
Test to: FCC Parts 2, 15 and 87


MODEL: MCX-1000A  
SN: Y1139  
FCC ID#: ASY MCX-1000A

Page 5 of 6


Honeywell MCX1000A Internal Photos 1/9/2006



Synthesizer Top side



Synthesizer Bottom side



Note there are no components located on printed circuit board sides not show in these photographs.

ROGERS LABS, INC.

4405 West 259<sup>th</sup> Terrace

Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Honeywell International Inc.

PN: 42455-1

Test #: 051212

Test to: FCC Parts 2, 15 and 87

MODEL: MCX-1000A

SN: Y1139

FCC ID#: ASY MCX-1000A

Page 6 of 6

Honeywell MCX1000A Internal Photos 1/9/2006