· ADVEXL10HD **MODEL**

DESCRIPTION: LABEL LOCATION ON UNIT

ADVENT


CUSTOMER

REVISION

DATE : 04/01/2018

PAGE : __5__ OF ___11_

FRONT VIEW



1. LOGO PLATE (32 x 6.5MM) (50-NH-20010G)



3. MODEL LABEL (32 x 5MM) (90-8B-10100G)

Model: ADVEXL10HD

2. WARNING LABEL (90x 70MM) (90-2S-02010G)


WARNING

An LCD panel and/or video monitor may be installed in a motor vehicle and visible to the driver if the LCD panel or video monitor is used for vehicle information, system control, rear or side observation or navigation. If the LCD panel or video monitor is used for television reception, video or DVD play, the LCD panel or video monitor must be installed so that these features will only function when the vehicle is in 'park' or when the vehicle's parking brake is applied.

An LCD panel or video monitor used for television reception. video or DVD play that operates when the vehicle is in gear or when the parking brake is not applied must be installed to the rear of the driver's seat where it will not be visible, directly or indirectly, to the operator of the motor vehicle.


NOTE: This label is to be removed by the end user only!

BACK VIEW



4. MODEL PLATE (52 x 80MM)

(50-8B-101A0G)



conditions: (1) This device may not cause harmful interference and (2) This device must accept any interference that may be received, including interference that may cause undesired operation.

This product is Class 1 Laser Product and complies with FDA Rules 21 CFR Chapter 1. Subchapter J.

Patented, refer to www.voxxintl.com/company/patents

FCC ID: ATI9R3ODM71011

5. BC S/N LBL XXX-XXX - POD



6. WARNING LBL 4 MOBILE VID LBL 89*74MM ADV 90-K0-00040G)

WARNING:

When installing this overhead monitor there should be no obstructions such as extra cabling, power chokes or any other objects placed between this overhead and the supplied mounting bracket. Failure to comply may cause damage to the overhead monitor and will void the warranty.



ADVERTENCIA:

Al instalar este monitor elevado, no debe haber obstrucciones, como por ejemplo, cables extra, inductores de potencia o ningún otro objeto ubicado entre este monitor elevado y el soporte de montaje proporcionado. El incumplimiento puede provocar daños al monitor elevado e invalidará la garantía.

AVERTISSEMENT:

Lors de l'installation de ce moniteur suspendu, il ne devrait y avoir aucune obstruction comme du câblage supplémentaire, des bobines de réactance d'alimentatior ou tout autre obiet placé entre ce dispositif suspendu et les supports de montage fournis Le défaut de se conformer peut causer un dommage au moniteur suspendu et annulera la garantie.