



# Intertek Testing Services

## ETL SEMKO

Report No.: 0109969

Tested By: Ben, Report No.: 0109969


Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF 60dB

Final Measurement: x QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



# Intertek Testing Services

ETL SEMKO

Report No.: 0109969

Tested By: Ben, Report No.: 0109969

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.45000	24.3	48.0
0.63500	24.0	48.0
0.76500	19.8	48.0

\* limit exceeded