


APPENDIX B-Page 1 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303


B.1 Radiated Measurement at Chamber

Frequency Below to 1GHz

Lie



Side




File Number: C1M2310191

Report Number: EM-F230632



AUDIX Technology Corp. No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan APPENDIX B-Page 2 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

Stand



Frequency Above to 1GHz Lie



File Number: C1M2310191

Report Number: EM-F230632




AUDIX Technology Corp. No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan APPENDIX B-Page 3 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

Side



Stand



File Number: C1M2310191


Report Number: EM-F230632



New Taipei City244, Taiwan

APPENDIX B-Page 4 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 RF Conducted Measurement



File Number: C1M2310191

Report Number: EM-F230632