

Response for B32OMNI3750G

1. has been re-uploaded
2. CDMA is deleted in the updated block diagram
3. 802.11 is deleted
4. Its RF board will be always sold with the end product.
5. will be modified tomorrow
6. the same to item 5
7. one of them has been deleted.
8. has been re-uploaded
9. the module has tri-band, however, it will disable the band outside the USA on the end product.
10. has been updated
11. Will issue part 68 DoC
12. it is typo, has been updated
13. has been uploaded with a separated file
14. changing bandwidth to channel spacing in the updated report.