



HERMON LABORATORIES

June 7, 2007

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated June 7, 2007; VeriFone Inc.
FCC ID: B32QX100, ATCB004977

Dear Mr. Johnson,
Please find below the answer to your questions.

- 1) Users Manual was corrected for Class B, the FCC statement as per 15.19(a)(3) inserted on page 1 (the EUT construction does not permit to place the full statement on the label). The file "User_manual_17525_rev1" was uploaded on June 7, 2007.
- 2) The FCC symbol was deleted from the label, because the EUT does not have connection to PC. As Operational Description defines: "The QX100 readily connects to any electronic payment device via an RS-232 or USB interface." The corrected file "Label_location_17525_rev1" was uploaded on June 7, 2007
- 3) The same as above.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories