



M. Flom Associates, Inc. - Global Compliance Center

3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176

www.mflom.com general@mflom.com (480) 926-3100, FAX: 926-3598

January 2, 2002

Applicant: Datron World Communications, Inc.
FCC ID: B3TG25RPV100 EA102146
Correspondence No.: 21606

Attention: Martin Perrine

EMC

Question 2) Change in Manual Page 12 re: paragraph "Channel Setup Sub Menu" 4th sentence will be changed to read "Channels will be selectively locked by manufacturer so that values cannot be changed from the radios keypad." The Operating Instructions per paragraph Factory Programming states: "It is not possible to program these radios from their keypads", in keeping with FCC Rules 47 CFR 90.203(e) and (g).

3) The programming instructions provided by the Applicant allow only ± 12.5 kHz digital bandwidth (but not ± 25 kHz)*. Please delete reference to emission designator 16K0F1E.

*Bn = $2(M + D) = 2(4.8 + 1.5) = 12.6$

4) 16K0F1E Deleted.

SAR

Is the head not considered part of the body? If the head is considered as part of the body, the SAR test and setup and separation distance of 1.5 cm is shown in the SAR report on page 4. Please confirm this with Kwok Chan and/or Richard Fabina.

We have been informed that these delays in not granting Certification are causing costly serious marketing circumstances for the Applicant.

We would appreciate a prompt reply.

Sincerely yours,

Morton Flom, P. Eng.