

Dan,

As discussed, the two (2) conducted emissions which did not comply with the average limit with a peak detector were remeasured utilizing a CISPR compliant receiver.

The average readings were found to be:

24.00 MHz	48 dBuV (Average)
24.88 MHz	36 dBuV (Average)

I trust that this resolves this outstanding issue.

Thank you,

Richard J. Reitz  
Laboratory Manager  
Retlif Testing Laboratories  
795 Marconi Avenue  
Ronkonkoma, NY 11779  
(631) 737-1500 x 28  
(631) 737-1497 fax  
[www.retlif.com](http://www.retlif.com)

CONFIDENTIALITY : This e-mail and any attachments are confidential and may be privileged. If you are not a named recipient, please notify the sender immediately and do not disclose the contents to another person, use it for any purpose or store or copy the information in any medium.