





Error: X-10 RMP File Not Found	SYSTEM X-10 LIMITED		
	Title: 2.4GHz VIDEO SENDER (MINIDin)		
	Number: 851001H11137	Revision: D	
	File Name: A:\MINITX-D.SCH		
	Date: 5-Nov-2002	Drawn By: Ian Wong	Sheet 1 of 1

Error: X-10.BMP File Not Found




OPTION



ECN	C18-0p E12-1p C17-C23-0.1p	IMPROVING MFG QW DUE TO PCB TRACK WITH ERROR
ECN	423 DSE - FOR ETSI APPROVAL	
ECN	DESCRIPTION	

COMPANY		SYSTEM X-10 LIMITED	
TITLE		MOD	
ADDRESS		851001H11119	
DATE	DDMM	SIZE	BANKING IN:
0	90	A4	SCH.CAMTX1H2
			REV
			03
SCALE: IN		PAGE 1 OF 1	



Title RF BOARD			Protel Technology Inc.	
Size: A4	Number:	Revision:		
File: A:\RF433.SCH	Date: 5-Nov-2002	Time: 16:27:40		
Sheet 1 of 1				