## **Interactive Technologies Inc**

## **EXHIBIT A ID** Label / Location



## Household Fire and Burglary Warning System Control Unit

S4006

ISSUE NO: AE6497

01/30/02

Model: 60-879

Input:3.6VDC

Board Number: 57-786

This Equipment should be installed in accordance with chapter 2 of the National Fire Alarm Code ANSI/NFPA 72-1993 (National Fire Protection Association, Batterymarch Park, Quincy, MA 02669) INTERNAL BATTERY: 3.6VDC The battery is automatically tested every 4 hours. REPLACE BATTERY EVERY 3-5 YEARS WITH EXACT REPLACEMENT ONLY: Saft LS 14500C Wiring Diagram: See installation Manual 466-1849. This system is intended to be checked by a qualified technician at least every three years.

This device complies with FCC rules Part 15. Operation is subject to the following two conditions: 1)this device may not cause harmful interference and (2) this device must accept any interference that maybe received, including interference that may cause undesired operation.

WARNING:

Complies with Part 68 FCC Rules FCC Reg. No. B42AL01B46059 Ringer Equivalence 0.3B (AC) Load Number 0.1

FCC ID: B4Z-786A-DTIM Canada IC: 867A 12000

Interactive Technologies Inc. North St. Paul, MN 55104

DISCONNECT TELCO BEFORE SERVICING. CAUTION: IMPROPER CONNECTIONS MAY RESULT IN DAMAGE TO THE EQUIPMENT.

US Patents xxxxxxxxx and others pending

42-248-xx

02/11/02 7:53 AM FCC ID: B4Z-786A-DTIM C:\WINNT\Profiles\Kenl.Nelson\Desktop\FCC Documintation\Submittles\DTIM\peices\id label.DOC