

From: Doug Kramer [mailto:dkramer@nceelabs.com]
Sent: Thursday, April 22, 2004 9:53 AM
To: dward ATCB
Subject: RE: B5D-CPE50MW_ATCB001275

Dennis,
Yes, that is correct, is that information that should be included somewhere in the report and if so, do you have any suggestions?
Doug

-----Original Message-----

From: dward ATCB [mailto:dward@americantcb.com]
Sent: Thursday, April 22, 2004 11:46 AM
To: 'Doug Kramer'
Subject: RE: B5D-CPE50MW_ATCB001275

Hi Doug
Your numbers don't add up in the tables for radiated emissions. They appear to be off a little. I am assuming that it is because they are from actual 2 decimal calculations while the table for the transducer and cables only have 1 decimal place. Is this correct???
Dennis