



M. Flom Associates, Inc. - Global Compliance Center

3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176

www.mflom.com general@mflom.com (480) 926-3100, FAX: 926-3598

February 4, 2002

Subject: Re: Telex FCC ID: B5DH216 EA158095

Re: To Correct Equipment Code

The equipment code DXX was incorrectly placed on Form 731. It should have been TNF. Thank you for your quick response in correcting this issue.

Please inform us of when the change has been made so that payment and a corrected Form 159 can be mailed to Mellon Bank to avoid having to resubmit the application.

Sincerely,
M. Flom Associates, Inc.