

**PHOTOGRAPH SECTION - EXTERNAL
FOR RFI TEST REPORT SERIAL NO:
RFI/MPTB1/RP44801JD01A**

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

S.No: RFI/MPTB1/RP44801JD01A

Page 2 of 4

Issue Date: 12 June 2003

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 24: 2002

This page has been left intentionally blank.

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 24: 2002

Photographs of EUT

This appendix contains the following photographs:

Photo Reference Number	Title
PHT/44801JD01/001	Front View of RBS2308 Cabinet with Shields & Mounting Base
PHT/44801JD01/002	Front View of RBS2308 Cabinet Mounting Base Shields Removed
PHT/44801JD01/003	Open View of RBS2308 Cabinet Mounting Base Shields Removed
PHT/44801JD01/004	Rear View of RBS2308 Cabinet Mounting Base Shields Removed
PHT/44801JD01/005	Front View of IXU21
PHT/44801JD01/006	Rear View of IXU21
PHT/44801JD01/007	Front View of RRU-H Edge
PHT/44801JD01/008	Rear View of RRU-H Edge

These pages are not included in the total number of pages for this report.

RADIO FREQUENCY INVESTIGATION LTD.

Operations Department

**Test Of: Ericsson AB.
RBS 2308
To: FCC Part 24: 2002**

TEST REPORT

S.No: RFI/MPTB1/RP44801JD01A

Page 4 of 4

Issue Date: 12 June 2003

This page has been left intentionally blank.

RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/001 Front View of RBS2308 Cabinet with Shields & Mounting Base



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/002 Front View of RBS2308 Cabinet Mounting Base Shields Removed



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department


Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/003 Open View of RBS2308 Cabinet Mounting Base Shields Removed



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/004 Rear View of RBS2308 Cabinet Mounting Base Shields Removed



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/005 Front View of IXU21



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

Photograph Section


S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/006 Rear View of IXU21



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/007 Front View of RRU-H Edge



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/008 Rear View of RRU-H Edge

