

**PHOTOGRAPH SECTION - INTERNAL
FOR RFI TEST REPORT SERIAL NO:
RFI/MPTB1/RP44801JD01A**

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

RADIO FREQUENCY INVESTIGATION LTD.

Operations Department

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 24: 2002

TEST REPORT

S.No: RFI/MPTB1/RP44801JD01A

Page 2 of 4

Issue Date: 12 June 2003

This page has been left intentionally blank.

Test Of: Ericsson AB.
RBS 2308
To: FCC Part 24: 2002

Photographs of EUT

This appendix contains the following photographs:

| Photo Reference Number | Title |
|------------------------|--------------------------------------|
| PHT/44801JD01/001 | Open View of RRU-H Edge |
| PHT/44801JD01/002 | Front View of Radio Access Board 1 |
| PHT/44801JD01/003 | Rear View of Radio Access Board 1 |
| PHT/44801JD01/004 | Front View of Radio Access Board 2 |
| PHT/44801JD01/005 | Rear View of Radio Access Board 2 |
| PHT/44801JD01/006 | Front View of Digital Radio Board 1 |
| PHT/44801JD01/007 | Rear View of Digital Radio Board 1 |
| PHT/44801JD01/008 | Front View of Digital Radio Board 2 |
| PHT/44801JD01/009 | Rear View of Digital Radio Board 2 |
| PHT/44801JD01/010 | Front View of Duplex Filter 1 |
| PHT/44801JD01/011 | Rear View of Duplex Filter 1 |
| PHT/44801JD01/012 | Front View of Duplex Filter 2 |
| PHT/44801JD01/013 | Rear View of Duplex Filter 2 |
| PHT/44801JD01/014 | Front View of Heater |
| PHT/44801JD01/015 | Rear View of Heater |
| PHT/44801JD01/016 | Top View of PSU |
| PHT/44801JD01/017 | Bottom View of PSU |
| PHT/44801JD01/018 | Internal View of PSU |
| PHT/44801JD01/019 | Top View of Power Interface Board |
| PHT/44801JD01/020 | Bottom View of Power Interface Board |
| PHT/44801JD01/021 | Top View of Y Interface Board |
| PHT/44801JD01/022 | Bottom View of Y Interface Board |
| PHT/44801JD01/023 | Top View of Radio Interface Board |
| PHT/44801JD01/024 | Bottom View of Radio Interface Board |

These pages are not included in the total number of pages for this report.

RADIO FREQUENCY INVESTIGATION LTD.

Operations Department

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 24: 2002

TEST REPORT

S.No: RFI/MPTB1/RP44801JD01A

Page 4 of 4


Issue Date: 12 June 2003

This page has been left intentionally blank.

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/001 Open View of RRU-H Edge



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department


Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/002 Front View of Radio Access Board 1



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/003 Rear View of Radio Access Board 1



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/004 Front View of Radio Access Board 2



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department

Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/005 Rear View of Radio Access Board 2



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/006 Front View of Digital Radio Board 1



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/007 Rear View of Digital Radio Board 1



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/008 Front View of Digital Radio Board 2



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/009 Rear View of Digital Radio Board 2



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/010 Front View of Duplex Filter 1



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/011 Rear View of Duplex Filter 1



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/012 Front View of Duplex Filter 2



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/013 Rear View of Duplex Filter 2



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/014 Front View of Heater



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/015 Rear View of Heater



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/016 Top View of PSU



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/017 Bottom View of PSU



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Operations Department


Photograph Section

S.No: RFI/MPTB1/RP44801JD01A

Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/018 Internal View of PSU



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/019 Top View of Power Interface Board



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/020 Bottom View of Power Interface Board



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/021 Top View of Y Interface Board



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002


PHT/44801JD01/022 Bottom View of Y Interface Board



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/023 Top View of Radio Interface Board



Test Of: Ericsson AB.
RBS 2308

To: FCC Part 24: 2002

PHT/44801JD01/024 Bottom View of Radio Interface Board

