



**EXTERNAL PHOTOGRAPH SECTION  
FOR RFI TEST REPORT SERIAL NO:  
RFI/MPTB1/45184JD06A**

Test Of: Ericsson AB.  
RBS 2308 1900 MHz R5B

To: FCC Part 24: 2003

Radio Frequency Investigation Ltd, Ewhurst Park, Ramsdell,  
Basingstoke, Hampshire, RG26 5RQ, ENGLAND.  
Tel: +44 (0) 1256 851193 Fax: +44 (0) 1256 851192

Registered in England, No. 211 7901.  
Registered Office: Ewhurst Park, Ramsdell,  
Basingstoke, Hampshire RG26 5RQ



**RADIO FREQUENCY INVESTIGATION LTD.**

**Conformance Testing Department**

**Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003**

**TEST REPORT**

**External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A**

---

This page has been left intentionally blank.

**RADIO FREQUENCY INVESTIGATION LTD.****Conformance Testing Department****TEST REPORT****External Photograph Section****S.No: RFI/MPTB1/RP45184JD06A**

**Test Of: Ericsson AB.**  
**RBS 2308 1900MHz R5B**  
**To: FCC Part 24: 2003**

---

This section contains the following photographs:

Photo reference number	Title
PHT/45184JD06/001	Front view of RBS2308 Cabinet with shields and mounting base.
PHT/45184JD06/002	Front view of RBS2308 Cabinet within mounting base.
PHT/45184JD06/003	Open view of RBS2308 Cabinet within mounting base.
PHT/45184JD06/004	Back view of RBS2308 Cabinet within mounting base.
PHT/45184JD06/005	Front view of Mounting base.
PHT/45184JD06/006	Front view of IXU21.
PHT/45184JD06/007	Back view of IXU21.
PHT/45184JD06/008	Front view of RRU-M EDGE
PHT/45184JD06/009	Back view of RRU-M EDGE

RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003

TEST REPORT

External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A

---

PHT/45184JD06/001 Front view of RBS2308 Cabinet with shields and mounting base.



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT

Conformance Testing Department

External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A

Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003

---

PHT/45184JD06/002 Front view of RBS2308 Cabinet within mounting base.



**RADIO FREQUENCY INVESTIGATION LTD.**

**Conformance Testing Department**

**Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003**

**TEST REPORT**

**External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A**

**PHT/45184JD06/003 Open view of RBS2308 Cabinet within mounting base.**



RADIO FREQUENCY INVESTIGATION LTD.

TEST REPORT


Conformance Testing Department

External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A

Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003

---

PHT/45184JD06/004 Back view of RBS2308 Cabinet within mounting base.






Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003

---

PHT/45184JD06/005 Front view of Mounting base.





**RADIO FREQUENCY INVESTIGATION LTD.**

**Conformance Testing Department**


**Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003**

**TEST REPORT**

**External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A**

---

**PHT/45184JD06/006 Front view of IXU21.**



**RADIO FREQUENCY INVESTIGATION LTD.**

**Conformance Testing Department**


**Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003**

**TEST REPORT**

**External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A**

---

**PHT/45184JD06/007 Back view of IXU21.**



**RADIO FREQUENCY INVESTIGATION LTD.**

**Conformance Testing Department**

**Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003**

**TEST REPORT**

**External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A**

---

**PHT/45184JD06/008 Front view of RRU-M EDGE.**





**RADIO FREQUENCY INVESTIGATION LTD.**

**Conformance Testing Department**

**Test Of: Ericsson AB.  
RBS 2308 1900MHz R5B  
To: FCC Part 24: 2003**

**TEST REPORT**

**External Photograph Section  
S.No: RFI/MPTB1/RP45184JD06A**

---

**PHT/45184JD06/009 Back view of RRU-M EDGE.**

