



**INTERNAL PHOTOGRAPH SECTION
FOR RFI TEST REPORT SERIAL NO:
RFI/MPTB1/45184JD06A**

Test Of: Ericsson AB.
RBS 2308 1900 MHz R5B

To: FCC Part 24: 2003

Radio Frequency Investigation Ltd, Ewhurst Park, Ramsdell,
Basingstoke, Hampshire, RG26 5RQ, ENGLAND.
Tel: +44 (0) 1256 851193 Fax: +44 (0) 1256 851192

Registered in England, No. 211 7901.
Registered Office: Ewhurst Park, Ramsdell,
Basingstoke, Hampshire RG26 5RQ



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

This page has been left intentionally blank.

Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

This section contains the following photographs:

Photo reference number	Title
PHT/45184JD06/001	Open view of RRU-M EDGE
PHT/45184JD06/002	Front view of Radio Access Board 1
PHT/45184JD06/003	Back view of Radio Access Board 1
PHT/45184JD06/004	Front view of Radio Access Board 2
PHT/45184JD06/005	Back view of Radio Access Board 2
PHT/45184JD06/006	Front view of Digital Radio Board 1
PHT/45184JD06/007	Back view of Digital Radio Board 1
PHT/45184JD06/008	Front view of Digital Radio Board 2
PHT/45184JD06/009	Back view of Digital Radio Board 2
PHT/45184JD06/010	Front view of Duplex Filter 1
PHT/45184JD06/011	Back view of Duplex Filter 1
PHT/45184JD06/012	Front view of Duplex Filter 2
PHT/45184JD06/013	Back view of Duplex Filter 2
PHT/45184JD06/014	Front view of Heater
PHT/45184JD06/015	Back view of Heater
PHT/45184JD06/016	Top view of Power Supply Unit
PHT/45184JD06/017	Bottom view of Power Supply Unit
PHT/45184JD06/018	Internal view of Power Supply Unit
PHT/45184JD06/019	Front view of Power Interface Board
PHT/45184JD06/020	Back view of Power Interface Board
PHT/45184JD06/021	Top view of Y Interface Board
PHT/45184JD06/022	Bottom view of Y Interface Board
PHT/45184JD06/023	Top view of Radio Interface Board
PHT/45184JD06/024	Bottom view of Radio Interface Board
PHT/45184JD06/025	FCC ID Label

These pages are not included in the total number of pages for this report.

RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/001 Open view of RRU-M EDGE.



Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

PHT/45184JD06/002 Front view of Radio Access Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/003 Back view of Radio Access Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/004 Front view of Radio Access Board 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/005 Back view of Radio Access Board 2.



Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

PHT/45184JD06/006 Front view of Digital Radio Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/007 Back view of Digital Radio Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/008 Front view of Digital Radio Board 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/009 Back view of Digital Radio Board 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/010 Front view of Duplex Filter 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/011 Back view of Duplex Filter 1.



Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

PHT/45184JD06/012 Front view of Duplex Filter 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/013 Back view of Duplex Filter 2.



RADIO FREQUENCY INVESTIGATION LTD.


Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

**Internal Photograph Section
S.No: RFI/MPTB1/RP45184JD06A**

PHT/45184JD06/014 Front view of Heater



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/015 Back view of Heater



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/016 Top view of Power Supply Unit



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/017 Bottom view of Power Supply Unit



RADIO FREQUENCY INVESTIGATION LTD.


Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT


**Internal Photograph Section
S.No: RFI/MPTB1/RP45184JD06A**

PHT/45184JD06/018 Internal view of Power Supply Unit



Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

PHT/45184JD06/019 Front view of Power Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/020 Back view of Power Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/021 Top view of Y Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/022 Bottom view of Y Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/023 Top view of Radio Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department


**Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003**

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/024 Bottom view of Radio Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

Test Of: Ericsson AB.
RBS 2308 1900MHz R5B
To: FCC Part 24: 2003

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB1/RP45184JD06A

PHT/45184JD06/025 FCC ID Label

