

# EXTERNAL PHOTOGRAPH SECTION FOR RFI TEST REPORT SERIAL NO: RFI/MPTB2/45184JD05A

Test Of: Ericsson AB. RBS 2308 850 MHz R5B

To: FCC Part 22: 2002



**Conformance Testing Department** 

Test Of: Ericsson AB. RBS 2308

To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 2 of 11

Issue Date: 15 October 2003

# **Photographs of EUT**

This section contains the following photographs:

Photo Reference Number	Title
PHT/45184JD05/001	Front view of RBS2308 Cabinet with shields and mounting base.
PHT/45184JD05/002	Front view of RBS2308 Cabinet within mounting base.
PHT/45184JD05/003	Open view of RBS2308 Cabinet within mounting base.
PHT/45184JD05/004	Back view of RBS2308 Cabinet within mounting base.
PHT/45184JD05/005	Back view of Mounting base.
PHT/45184JD05/006	Front view of IXU21.
PHT/45184JD05/007	Back view of IXU21.
PHT/45184JD05/008	Front view of RRU-M EDGE
PHT/45184JD05/009	Back view of RRU-M EDGE

**Conformance Testing Department** 

Test Of: Ericsson AB. RBS 2308

To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 3 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/001 Front view of RBS2308 Cabinet with shields and mounting base.



**Conformance Testing Department** 

Test Of: Ericsson AB.

RBS 2308
To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 4 of 11

Issue Date: 15 October 2003

### PHT/45184JD05/002 Front view of RBS2308 Cabinet within mounting base.



**Conformance Testing Department** 

Test Of: Ericsson AB. RBS 2308

To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 5 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/003 Open view of RBS2308 Cabinet within mounting base.



**Conformance Testing Department** 

Test Of: Ericsson AB.

RBS 2308
To: FCC Part 22: 2002


**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 6 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/004 Back view of RBS2308 Cabinet within mounting base.



**Conformance Testing Department** 

Test Of: Ericsson AB.

RBS 2308
To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 7 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/005 Back view of Mounting base.



**Conformance Testing Department** 

Test Of: Ericsson AB.

**RBS 2308** 

To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 8 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/006 Front view of IXU21.



**Conformance Testing Department** 

Test Of: Ericsson AB.

**RBS 2308** 

To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 9 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/007 Back view of IXU21.



**Conformance Testing Department** 

Test Of: Ericsson AB. RBS 2308

To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 10 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/008 Front view of RRU-M EDGE.



**Conformance Testing Department** 

Test Of: Ericsson AB. RBS 2308

To: FCC Part 22: 2002

**TEST REPORT** 

S.No: RFI/MPTB2/RP45184JD05A

Page 11 of 11

Issue Date: 15 October 2003

# PHT/45184JD05/009 Back view of RRU-M EDGE.

