


Test Of: Ericsson AB  
RBS 2308 1900 MHz  
To: FCC Part 24: 2005

---


PHT/71622JD11/026 Y Interface Board. Front View



Test Of: Ericsson AB  
RBS 2308 1900 MHz  
To: FCC Part 24: 2003


---

PHT/71622JD11/027 Y Interface Board. Back View



Test Of: Ericsson AB  
RBS 2308 1900 MHz  
To: FCC Part 24: 2005


PHT/71622JD11/028 Power Interface Board. Front View



Test Of: Ericsson AB  
RBS 2308 1900 MHz  
To: FCC Part 24: 2003

---

PHT/71622JD11/029 Power Interface Board. Back View



Test Of: Ericsson AB  
RBS 2308 1900 MHz  
To: FCC Part 24: 2005

---


PHT/71622JD11/030 Radiated Spurious Emissions 1



Test Of: Ericsson AB  
RBS 2308 1900 MHz  
To: FCC Part 24: 2003

---

PHT/71622JD11/031 Radiated Spurious Emissions 2



**RFI GLOBAL SERVICES LTD**

**TEST REPORT**

**S.No. RFI/MPTE1/RP71622JD11A**

**Page: 174 of 174**

**Issue Date: 16 August 2006**

**Test Of: Ericsson AB  
RBS 2308 1900 MHz**

**To: FCC Part 24: 2005**

---

This page has been left intentionally blank.