


Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

---

PHT/71622JD21/015 Digital Radio Access Board 2. Front View






Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

---

PHT/71622JD21/016 Digital Radio Access Board 2. Back View






Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

---

PHT/71622JD21/017 Duplex Filter 1. Front View






Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

---

PHT/71622JD21/018 Duplex Filter 1. Back View






Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

---

PHT/71622JD21/019 Duplex Filter 2. Front View






Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

---


PHT/71622JD21/020 Duplex Filter 2. Back View



Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

---


PHT/71622JD21/021 PSU. Front View





Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

PHT/71622JD21/022 PSU. Back View





Test Of: Ericsson AB  
RBS 2308 850 MHz  
To: FCC Part 22: 2005

PHT/71622JD21/023 PSU. Internal View

