



Test Of: Ericsson AB
RBS 2308 850 MHz
To: FCC Part 22: 2005

PHT/71622JD21/024 Radio Interface Board. Front View




Test Of: Ericsson AB
RBS 2308 850 MHz
To: FCC Part 22: 2005

PHT/71622JD21/025 Radio Interface Board. Back View




Test Of: Ericsson AB
RBS 2308 850 MHz
To: FCC Part 22: 2005

PHT/71622JD21/026 Y Interface Board. Front View




Test Of: Ericsson AB
RBS 2308 850 MHz
To: FCC Part 22: 2005

PHT/71622JD21/027 Y Interface Board. Back View



Test Of: Ericsson AB
RBS 2308 850 MHz
To: FCC Part 22: 2005


PHT/71622JD21/028 Power Interface Board. Front View



Test Of: Ericsson AB
RBS 2308 850 MHz

To: FCC Part 22: 2005

PHT/71622JD21/029 Power Interface Board. Back View




Test Of: Ericsson AB
RBS 2308 850 MHz
To: FCC Part 22: 2005

PHT/71622JD21/030 Radiated Spurious Emissions 1



Test Of: Ericsson AB
RBS 2308 850 MHz
To: FCC Part 22: 2005

PHT/71622JD21/031 Radiated Spurious Emissions 2



RFI GLOBAL SERVICES LTD

TEST REPORT

S.No: RFI/MPTE1/RP71622JD21A

Page: 150 of 150

Issue Date: 16 August 2006

**Test Of: Ericsson AB
RBS 2308 850 MHz**

To: FCC Part 22: 2005

This page has been left intentionally blank.