HP Inc.

3390 East Harmony Road Fort Collins 80528 Colorado United States

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Date: 2019-06-13

Reference: FCC ID: B94-AX201D2WS

## To The Commission:

This Change of Identification request applies for a new FCC ID: B94-AX201D2WS as established in 47CFR 2.933(b) for a currently approved device. This application by HP Inc. will establish a new FCC ID under B94 grantee code for purpose of marketing. The original grant to FCC ID: PD9AX201D2 will remain in effect.

An authorization letter by Intel Mobile Communications is attached.

Per 2.933(b)

- 1. The original identification is FCC ID: PD9AX201D2.
- 2. The original grant date is 11/20/2018.
- 3. The equipment is electrically identical. Only the FCC ID number is different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.
- 6. We are responsible for any changes and will not alter or offer any capabilities that will modify DFS settings

The following files are electronically submitted as attachments:

**Cover Letter** 

**External Photos** 

FCC ID label format and location

Sincerely yours,

Richard P Tarsio

HP Inc.

Tel: 1 512 319 7260

Richard P Tarsio

E-mail: peter.tevlin@hp.com