



HP Inc.
3390 East Harmony Road
Mailstop 66
Fort Collins, CO 80528

hp.com

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Certification and Engineering Bureau
ISED Canada
3701 Carling Avenue (Building 94)
Ottawa, Ontario
K2H 8S2

Date: 2021-07-12
Subject: Request to change in Identification

To Whom It May Concern:

This application for Change of Identification request a new FCC ID as stipulated in 47 CFR 2.933 (b) for presently authorized equipment.

This application by HP Inc. will establish a new FCC ID: B94-PF002WA, a new IC: 466C-PF002WA, PMN: HyperX Pulsefire Haste Wireless adapter, HVIN: PF002WA, FVIN: N/A for the purpose of marketing.

The original grant to Kingston Technology Company FCC ID: JIC-PF002WA, IC: 3880A-PF002WA, PMN: HyperX Pulsefire Haste Wireless adapter, HVIN: PF002WA, FVIN: N/A will remain in effect.

Per 47 CFR 2.933 (b)

- 1) The original identification is FCC ID: JIC-PF002WA.
- 2) The original grant date is 2021/04/08.
- 3) The equipment is electrically and functionally identical. Only the applicant, label, and FCC ID number are different.
- 4) The original test results are applicable and representative of this change ID device.
- 5) Exterior photographs are included in this application.

Sincerely,

By: Vanessa Tsai
(Signature)

Vanessa Tsai / Product Compliance Engineer
(Print name / Title)