



FCC ID: B94CLX4195FW

Label & Label Location

| | | |
|---|--|--|
| <p>HP Inc. 11311 Chinden Blvd. Boise, ID 83714, USA</p>  <p>Product No. :XXXXXX Place : M264 USOC Jack Type:RJ11C</p> | <p>Model: Xpress C1860FW Volts: AC 110-127 V Hertz: 50/60 Hz Amps: 8 A Ringer Equivalence: 0.0B Manufactured: SEPTEMBER 2017</p> | <p>FCC ID : B94CLX4195FW Contains FCC ID : B94SPWB43143U This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: i) This device may not cause harmful interference, and ii) This device must accept any interference received, including interference that may cause undesired operation. Complies with Part 68, FCC Rules. US : 6DNFA00BSLC1860FW CAN ICES-3 (B)/NMB-3(B) This product complies with 21 CFR Chapter 1, subchapter J. Contains IC : 466I-SPWB43143U IC : 466I-CLX4195FW</p> |
| <p>M/C : SL-C1860FW/XAA</p>  <p>S/N : WWWWWW</p> |  <p>US E337632 I.T.E.</p> | <p>MADE IN CHINA Fabriqué en Chine</p> |
| <p>SSN : Z88KBJAD70001YW</p> | | |

Label



Label Location