



3390 East Harmony Road  
Fort Collins  
Colorado 80528  
United States

To whom it may concern:

This device with FCC ID: [B94HNI61CPA](#) integrates a CAT-M module:

	FCC ID	Equipment Class	Date of Grant	Rule Part
CAT-M module	ZMOFB520	PCS	09/02/2022	22/24/27/90

No hardware design changes are made on the module, and the software has not been changed to increase the RF output power of the module and provided host level antenna gain is less than the original module grant. Pursuant to KDB 996369 D02, the original modular report (Report Number details see below) are submitted to represent the compliance of Part 2/22/24/27/90 conducted/radiated testing items of this device. Worst radiated cases found in module level testing are performed on the host level to ensure the compliance is kept.

Modular Test Report Number	
SEWM2207000119RG01	SEWM2207000119RG03

  
\_\_\_\_\_  
Liang Rong Chiao  
Worldwide Technical Regulations  
HP International Pte. Ltd., Taiwan Branch  
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan  
[frances.liang@hp.com](mailto:frances.liang@hp.com)  
T : +886 2 3789-2469