



American Certification Body  
6731 Whittier Avenue Suite C110  
McLean, VA 22101  
USA

Date: 9/21/2019

Ref: Application for Original Equipment Authorization for FCC ID: B94-HNQ20PDCP2

Dear Examiner,

This is to request to dismiss grants issued under FCC ID: B94-HNQ20PDCP2.

This FCC ID was in error and will be superceded by FCC ID: B94HNQ20PDCP2.  
The error was a typo that inserted a (-) into the ID by mistake. All other documents  
are correct.

TC Numbers are as follows: TC217556, TC370399, TC535536, TC796417 and  
TC395621.

The product bearing the FCC ID/TCs in question have not been marketed or sold anywhere  
in the United States nor anywhere in the world..

Sincerely,

A handwritten signature in black ink, appearing to read 'Steven C. Hackett'.

Steven C. Hackett

Sr Regulatory Engineer, Intel Corporation acting as agent on behalf of HP Inc. 1501  
Page Mill Road Palo Alto, CA 94304