



3390 East Harmony Road
Fort Collins
Colorado 80528
United States

To whom it may concern:

This device with FCC ID: B94R2022GPKV integrates a WWAN module:

	FCC ID	Equipment Class	Date of Grant	Rule Part
WWAN module	ZMOFM350GL	CBE	04/08/2021	96
		PCB	04/09/2021	22/24/27/90

No hardware design changes are made on the module, and the software has not been changed to increase the RF output power of the module and provided host level antenna gain is less than the original module grant. Pursuant to KDB 996369 D02, the original modular report (Report Number details see below) are submitted to represent the compliance of Part 22/24/27/90/96 conducted/radiated testing items of this device. Worst radiated cases found in module level testing are performed on the host level to ensure the compliance is kept.

Modular Test Report Number				
FG051802A	FG051802B	FG051802C	FG051802D	FG051802E
FG051802F	FG051802G	FG051802H	FG051802I	FG051802J
FW051802				

Liang Rong Chiao
Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan
frances.liang@hp.com
T : +886 2 3789-2469