

FCC TEST REPORT Report No.: FR5O2016E-B

### **APPENDIX C. Photographs of Setup Photographs of Conducted Emission Test Configuration**



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

: C1 of C6 Page No. TEL: 886-2-2696-2468 Report Issued Date : Nov. 29, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01



SIDE VIEW

SPORTON International Inc.

Page No. : C2 of C6 TEL: 886-2-2696-2468 Report Issued Date : Nov. 29, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01

FCC TEST REPORT Report No.: FR5O2016E-B

## **Photographs of Radiated Emission Test Configuration**

### Antenna 6

Front View






: C3 of C6

Rear View

SPORTON International Inc.

Page No. TEL: 886-2-2696-2468 Report Issued Date : Nov. 29, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01

Front View






Rear View

SPORTON International Inc.

Page No. : C4 of C6 TEL: 886-2-2696-2468 Report Issued Date : Nov. 29, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01

Front View






Rear View

SPORTON International Inc.

Page No. : C5 of C6 TEL: 886-2-2696-2468 Report Issued Date : Nov. 29, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01



Front View




Rear View

SPORTON International Inc.


Page No. : C6 of C6 TEL: 886-2-2696-2468 Report Issued Date : Nov. 29, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01

FCC TEST REPORT Report No.: FR5O2016C-R1-B

# APPENDIX C. Photographs of Setup Photographs of Conducted Emission Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C6
Report Issued Date : Nov. 25, 2005
Report Version : Rev. 01




SIDE VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C6
Report Issued Date : Nov. 25, 2005
Report Version : Rev. 01

## **Photographs of Radiated Emission Test Configuration**

### Antenna 3

Front View






Rear View

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C6
Report Issued Date : Nov. 25, 2005
Report Version : Rev. 01

Front View






Rear View

SPORTON International Inc.

Page No. : C4 of C6 TEL: 886-2-2696-2468 Report Issued Date : Nov. 25, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01

502016

### Antenna 7



Front View




Rear View

SPORTON International Inc.

Page No. : C5 of C6 TEL: 886-2-2696-2468 Report Issued Date : Nov. 25, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01

Front View





Rear View

SPORTON International Inc.

Page No. : C6 of C6 TEL: 886-2-2696-2468 Report Issued Date : Nov. 25, 2005 FAX: 886-2-2696-2255 Report Version : Rev. 01