
FCC TEST REPORT Report No.: FR5O2016C-R1-A

APPENDIX C. Photographs of Setup Photographs of Conducted Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3
Report Issued Date : Nov. 25, 2005
Report Version : Rev. 01




SIDE VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Report Issued Date : Nov. 25, 2005
Report Version : Rev. 01

Photographs of Radiated Emission Test Configuration



Front View



Rear View

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3
Report Issued Date : Nov. 25, 2005
Report Version : Rev. 01

FCC TEST REPORT Report No.: FR5O2016E-A

APPENDIX C. Photographs of Setup Photographs of Conducted Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3
Report Issued Date : Nov. 29, 2005
Report Version : Rev. 01

FCC TEST REPORT Report No. : FR5O2016E-A



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Report Issued Date : Nov. 29, 2005
Report Version : Rev. 01

FCC TEST REPORT Report No.: FR5O2016E-A

Photographs of Radiated Emission Test Configuration



Front View



Rear View

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3

Report Issued Date : Nov. 29, 2005

Report Version : Rev. 01