



3390 East Harmony Road
Fort Collins
Colorado 80528
United States

October 5, 2022

Attestation

We, HP Inc., attest that FCC ID: **B94-RTL8852BER** complies with device protocol requirements and operational restrictions for Client Devices.

- 1) This device will not directly connect to another client device.
- 2) This device will only associate and connect with an indoor Access Point (AP) or indoor Subordinate.
- 3) This device will always be under the control of an indoor AP. However, there may exist situations where the client may transmit brief messages, prior to being under the control of an AP, to join an AP network. But these brief messages will only occur if the client has detected a signal confirming that an AP is operating on a particular channel. These brief messages will have a time-out mechanism if the client does not receive a response from an AP.

A handwritten signature in black ink that reads 'Liang Rong Chiao'.

Liang Rong Chiao

Worldwide Technical Regulations

HP International Pte. Ltd., Taiwan Branch

10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan

frances.liang@hp.com

T +886-2-37892469