

November 7, 2017

Subject: Request to Change in Identification.

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by HP Inc., will establish a new FCC ID under the HP Inc. grantee code (B94) for the purpose of marketing. The original grant to Samsung Electronics Co., Ltd. (FCC grantee code A3L) will remain in effect.

Per 2.933(b)

- 1. The original identifications of all grants are listed in the table on page 2 (Part 15B Certifications).
- 2. The original grant dates of all grants are listed in the table on page 2 (Part 15B Certifications).
- 3. All equipment is electrically identical. Only the model names, trade names, and FCC ID numbers are different.
- 4. All original test results are applicable and representative of the changed devices.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely,

Jonathan Rodriguez

USA/CAN Technical Regulations & Standards Engineer

World Wide Technical Regulations

HP Inc.



FCC Part 15B Certifications

The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.

FCC Grantee Code Change Request by HP Inc.

Issued: November 07, 2017

| | issueu. November (| | | | | | | JI, LUII | | | |
|----------|--------------------|-----------------|--------------|------------------------|----------|----------|-----------|-----------------|--------------|------------------------|--|
| Existing | Change to | Grantee Code | FCC ID | Original Grant Date | | Existing | Change to | Grantee Code | FCC ID | Original Grant Date | |
| Χ | | A3L | A3LCLP415NW | 4/23/2012 | | Χ | | A3L | A3LSLM2825DW | 1/7/2013 | |
| | Χ | B94 | B94CLP415NW | - | | | Χ | B94 | B94SLM2825DW | _ | |
| | | | | <u> </u> | | | | | | | |
| Χ | | A3L | A3LCLP680DW | 4/23/2012 | | Χ | | A3L | A3LSLM2875FW | 1/7/2013 | |
| | Χ | B94 | B94CLP680DW | - | | | Χ | B94 | B94SLM2875FW | - | |
| | | | | | | | | | | | |
| X | | A3L | A3LCLX4195FW | 4/20/2012 | <u> </u> | Χ | | A3L | A3LSLM3015DW | 10/8/2015 | |
| | Χ | B94 | B94CLX4195FW | - | | | Χ | B94 | B94SLM3015DW | _ | |
| | | | | | | | | | | | |
| X | | A3L | A3LCLX6260FW | 4/20/2012 | <u> </u> | Χ | | A3L | A3LSLM3065FW | 10/8/2015 | |
| | Χ | B94 | B94CLX6260FW | - | | | Χ | B94 | B94SLM3065FW | - | |
| | | | | | | | | | | | |
| Χ | | A3L | A3LML3750ND | 10/7/2011 | | Χ | | A3L | A3LSLM4025DW | 2/27/2013 | |
| | Χ | B94 | B94ML3750ND | - | | | Χ | B94 | B94SLM4025DW | - | |
| | | | | <u> </u> | | | | | | | |
| Χ | | A3L | A3LSLC2620DW | 6/19/2014 | | Χ | | A3L | A3LSLM4025NX | 7/19/2013 | |
| | Χ | B94 | B94SLC2620DW | - | | | Χ | B94 | B94SLM4025NX | - | |
| | | | | | • | | | | | | |
| X | | A3L | A3LSLC2670FW | 6/19/2014 | | Χ | | A3L | A3LSLM4030ND | 4/15/2015 | |
| | Χ | B94 | B94SLC2670FW | - | | | Χ | B94 | B94SLM4030ND | - | |
| | | | | | • | | | | | | |
| X | | A3L | A3LSLC430W | 4/9/2015 | | Χ | | A3L | A3LSLM4075FW | 2/27/2013 | |
| | Χ | B94 | B94SLC430W | - | | | Χ | B94 | B94SLM4075FW | - | |
| | | | | <u> </u> | | | | | | | |
| Χ | | A3L | A3LSLC480FW | 4/9/2015 | | Χ | | A3L | A3LSLM4075FX | 7/19/2013 | |
| | Χ | B94 | B94SLC480FW | - | | | Χ | B94 | B94SLM4075FX | - | |
| | | | | | | | | | | | |
| Χ | | A3L | A3LSLM2020W | 9/9/2013 | | Χ | | A3L | A3LSLM4530NX | 11/5/2014 | |
| | Χ | B94 | B94SLM2020W | - | | | Χ | B94 | B94SLM4530NX | - | |
| | | | | | ı | | | | | | |
| Χ | | A3L | A3LSLM2070FW | 4/14/2014 | | Χ | | A3L | A3LSF760P | 9/29/2011 | |
| | Χ | B94 | B94SLM2070FW | - | | | Χ | B94 | B94SF760P | - | |
| | | | | | | | | | | | |