

Electronics Testing Center, Taiwan

No. 8, Lane 29, Wenming Rd., Guishan Shiang, Taoyuan County, 33383, Taiwan, R.O.C.

Date: 6/13/2013

Federal Communications Commission

To Whom It May Concern:

We, Electronic Test Center Taiwan (ETC), ask to revise the test report on FCC website due to the typing error issue, which FCC ID is BABFT0044C. We acknowledge the typing error issue of the test results in the test report, page 78, which leads to incorrect and incompatible results. We confirm that the compliance of the device for FCC and IC rules is not affected.

10.4.3.1.2 IEEE 802.11g

Operation Channel	Test Frequency (MHz)	Reading (dBuV)				Factor (dB) Corr.	Result @3m (dBuV/m)		Limit @3m (dBuV/m)	
		H		V			Peak	Ave	Peak	Ave.
		Peak	Ave	Peak	Ave					
1	2390.000	38.4	23.8	34.3	18.1	30.3	68.7	54.1	74	54
11	2483.500	35.4	17.9	33.1	15.8	30.3	65.7	48.2	74	54

Test Date: Mar. 21, 2011 Temperature: 17°C Humidity: 54%

10.4.3.1.3 IEEE 802.11gn, H120

Operation Channel	Test Frequency (MHz)	Reading (dBuV)				Factor (dB) Corr.	Result @3m (dBuV/m)		Limit @3m (dBuV/m)	
		H		V			Peak	Ave	Peak	Ave.
		Peak	Ave	Peak	Ave					
1	2390.000	41.0	23.8	37.0	18.2	30.3	71.3	54.1	74	54
11	2483.500	36.2	18.0	32.9	16.0	30.3	66.5	48.3	74	54

ETC fully understand the situation and therefore will focus on preventive procedure to eliminate similar issue for future projects. ETC will follow all applicable test procedures. All the test results will be checked for correctness and accuracy prior to submitting the test report.

By:



(Signature)

Supervisor
EMC Testing Department I
Electronics Testing Center, Taiwan

By:

James Cheng

(Printed)