





5969 Robinson Avenue
Riverside, CA 92503
(909) 637-2630
FAX (909) 637-2704

FCC ID: BBD3-1AE-MAS
RV38004E

Output Power

DNB Job Number:	38004	Date:	July 16, 2002	Conformance Standards [X] FCC Part 15 [X] FCC Part 90
Customer:	TPL Communications			
Model Number:	PA3-1AE-MAS	Serial Number:	1000	
Description:	RF Amplifier			





5969 Robinson Avenue
Riverside, CA 92503
(909) 637-2630
FAX (909) 637-2704


FCC ID: BBD3-1AE-MAS
RV38004E

Antenna Conducted Spurious

DNB Job Number:	38004	Date:	July 16, 2002	Conformance Standards [X] FCC Part 15 [X] FCC Part 90
Customer:	TPL Communications			
Model Number:	PA3-1AE-MAS	Serial Number:	1000	
Description:	RF Amplifier			

FCC ID: BBD3-1AE-MAS REPORT: RV38004E M/N PAS-1AE-MAS
ANTENNA CONDUCTED SPURIOUS

MKR Δ 164 MHz
-67.30 dB





5969 Robinson Avenue
Riverside, CA 92503
(909) 637-2630
FAX (909) 637-2704

FCC ID: BBD3-1AE-MAS
RV38004E

Occupied Bandwidth

DNB Job Number:	38004	Date:	July 16, 2002	Conformance Standards [X] FCC Part 15 [X] FCC Part 90
Customer:	TPL Communications			
Model Number:	PA3-1AE-MAS	Serial Number:	1000	
Description:	RF Amplifier			

