



6500 West Cortland Street • Chicago, Illinois 60707 • 773-889-8870 • Fax: 773-794-1930

29 July, 2004

Timco TCB
849 NW State Road 45
Newberry, FL 32669.

Ref: FCC ID: BBO19DX

Dear Sirs:

With regard to the sample of CB radio bearing FCC ID BBO19DX submitted for testing on 25 June, 2004, the PLL integrated circuit used in this radio at the time of its initial grant has been discontinued by the manufacturer and is no longer available.

Cobra Electronics Corporation is requesting a Class II Permissive Change to allow the use of a new integrated circuit in the frequency control PLL circuit. The replacement PLL device is a current part from Sanyo and readily available.

Sincerely,

Robert Mudra

Robert Mudra
Engineering Manager