



6500 West Cortland Street • Chicago, Illinois 60707 • 773-889-8870 • Fax: 773-794-1930

03 July 2008

Timco Engineering, Inc.
849 NW State Road 45
P.O. Box 370
Newberry, Florida 32669

Reference Cobra Model Numbers:
CXR700, CXR720, CXR725, CXR750, CXR755, CXR756

New FCC Identifier: **BBOCXR700** (original FCC identifier BBOLI5600)

To Whom It May Concern:

Persuant to 47 CFR 2.933(b), Cobra Electronics Corporation requests modification of the FCC identifier, BBOLI5600 originally granted on 25 October, 2007 and associated with models LI5600, LI5590, LI5625, LI5650, and LI5675.



Figure 1

These model numbers have been changed to **CXR700, CXR720, CXR725, CXR750, CXR755, and CXR756**. For reasons of market differentiation, Cobra requests a new FCC identifier, **BBOCXR700** and Grant of Equipment Authorization be associated with these new models shown in Figure 1.

There are no electrical or mechanical revisions. The original test data supporting the Grant of Equipment Authorization BBOLI5600 remains representative of and applicable to the new model numbers. The new FCC identifier is being requested for market differentiation only.

The new identification label to be used with these models is shown below as Figure 2. The label location is the subject of a separate request to FCC to locate the label in the battery compartment of the radio. A reference image from that proposal is included as Figure 3




Figure 2



Figure 3

Sincerely,

Robert Mudra

Engineering Manager
Cobra Electronics Corporation