

Cobra Electronics Corporation  
6500 West Cortland St. Chicago IL. 60707

Oct. 4, 2001

Attn : Ms. Melissa Carter  
360 Herndon Parkway  
Herndon, VA 20170

Dear Melissa,

Upon I received FCC grant for Cobra FRS 105, I discovered that FCC ID number shown on the grant was incorrectly indicated as BBOFRS11B instead of intended BBOFRS105.

Although Maxon informed your lab (SY Park of Maxon e-mailed on 8/31) stating the ID should be as BBOFRS105), incorrect ID was mistakenly used on FCC sample units resulted in wrong ID being listed on Form 731. However, FCC ID number to be used on production units has already correctly printed as "BBOFRS105".

Therefore, I would like to request to correct ID on the Grant for model FRS 105 from BBOFRS11B to "**BBOFRS105**" as soon as possible as this ID was being used on all production units.

I also attached my credit card information for ATCB in an effort to obtain revised the grant promptly.

Sincerely,

Tom Ahn  
Director of Engineering and Overseas Development  
Cobra Electronics

CC: ATCB  
Maxon