

RICOH

810 Shimoimaizumi, Ebina-city,
Kanagawa 243-0460 Japan

December 21, 2007

**Federal Communication Commission
Equipment Authorization Division
Application Processing Branch
7435 Oakland Mills Road
Columbia, Maryland 21046**

Subject : Reassessment under Section 2.1043 of FCC Part 2
(Class II Permissive Change)
Company : Ricoh Company Ltd.
Product : Full Color MFP(Aficio MP C2500, Aficio MP C3000)
FCC ID : BBP-RFAT001

This is request on reassessment of the granted product (FCC ID: BBP-RFAT001) on October 18, 2005. We request the expansion of the followings.

1. To add the grant note that the additional measurement to verify co-location operation is performed. (Please see the attached test report)

The difference between the certified product and the modified one is the above only.

The device co-located with Full Color MFP (FCC ID: BBP-RFAT001) is already approved optional IEEE 802.11b/g interface unit (FCC ID: BBP-WLRW54G1).

Only one optional interface board can be installed in the Full Color MFP at a time.

Therefore, the optional IEEE 802.11b/g interface unit cannot be installed concurrently with another optional wireless interface.

Since this optional IEEE 802.11b/g interface unit is optional, all the necessary FCC regulatory statements for wireless device are included in users manual of IEEE 802.11b/g interface unit itself for users. Also, FCC ID label is visible before users install the unit to Full Color MFP.



Seiji Nakamura

Leader

EMC and Telecommunications Group