

January 12, 2011

Federal Communication Commission
Equipment Authorization Division
Application Processing Branch
7435 Oakland Mills Road
Columbia, Maryland 21046

Subject : Reassessment under Section 2.1043 of FCC Part 2
(Class II Permissive Change)
Company : Ricoh Company, Ltd.
Product : Color Laser Printer
Model : Aficio SP C430DN, LP137CN, CLP37DN, SP C430DN
Aficio SP C431DN, LP142CN, CLP42DN, SP C431DN
C230, LD130C, Aficio MP C300, C230SR, LD130CSR, Aficio MP C300SR
C240, LD140C, Aficio MP C400, C240SR, LD140CSR, Aficio MP C400SR
FCC ID : BBP-RFZEU01

This is request on reassessment of the granted product (FCC ID: BBP-RFZEU01) on February 24, 2010. We request the expansion of the followings.

1. To add the grant note that the additional measurement to verify co-location operation is performed. (Please see the attached test report)

The difference between the certified product and the modified one is the above only.

The device co-located with "Color Laser Printer" (FCC ID: BBP-RFZEU01) is already approved "Option(s) for Radiocommunications" (FCC ID: BBP-BT21A01).

Only one optional interface board can be installed in "Color Laser Printer" at a time.

Therefore, "Option(s) for Radiocommunications" cannot be installed concurrently with another optional wireless interface.

Since this "Option(s) for Radiocommunications" is optional, all the necessary FCC regulatory statements for wireless device are included in users manual of "Option(s) for Radiocommunications" itself for users. Also, FCC ID label is visible before users install the unit to "Color Laser Printer".



Taku Matsuyama

Group Leader

Ricoh Company, Ltd.