


APPENDIX 3: Photographs of test setup

Conducted Emission




Front




Rear

Radiated Spurious Emission

Below 1 GHz



Front



Rear

UL Japan, Inc.


Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401

Above 1 GHz



Front



Rear

Worst Case Position

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted test




Photo 1



Photo 2

End of Report

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401