



Date: August 13, 2018

We, CASIO COMPUTER CO., LTD., declare that the device does not support CH12 and CH13 in all the operational mode(s) for the following product. CH12 and CH13 will be disabled when the product is sold in the United States.

FCC ID: BBQ-YW41

If you should have any question(s) regarding this declaration, please don't hesitate to contact us. Thank you!

A handwritten signature in blue ink, appearing to read 'Hiroaki Suzuki', is written on a light yellow rectangular background.

Hiroaki Suzuki/ Manager
CASIO COMPUTER CO., LTD.
Tel: +81-42-579-7282
Fax: +81-42-579-7702
E-mail: suzu-h@casio.co.jp