

8


View only - use layout file for the laser etch machine.

7



1:1

6



4:1

METAL SHIELD  
CONNECTION LINE

5

4

Use "JP ICON" as reference to get the right size.

Use layout file as input for the laser etch machine.

3

Don't laser etch in the in the connection line of the metal shield.

Cosmetic Standard: GSC.ST.00002  
Part Marking.: GSC.PR.00102

### CONFIDENTIALITY NOTICE:

This document is the property of GN Netcom A/S and must be treated as confidential. The document must not be used, or disclosed to any third party, without written permission by GN Netcom A/S. Copyright © 2010 GN Netcom A/S. All rights reserved.

Process control dimensions are marked:

IQC/OQC Characteristics for Evaluation:

--

2

Date of Change:	Description of Change:	Responsible:
-----------------	------------------------	--------------

1



Matr. Spec: (See B.O.M.)	3D revision:	Created by:	Created on:	Tool marking:	Drawing Scale:	Size:
Matr. type:		ECAI	13-Feb-2017	.....	2:1	A4
GN PDM file:	Object type: PART	Approved by:	Approved on:	Units:	Projection:	
50-06747_REAR_HOUSING ver:J.1		Jayway H.	13-Feb-2017	mm		

Description:	Document No:	Doc. Revision:	Design Status:	Page No:
Placement LASER ETCH, BOTTOM_LINK 370	50-07962	B	Released	1 of 1

A B C D E F